



Figure 24. Enlarged aerial photograph of a portion of Dudley Island showing marsh shoreline transects and various shoreline positions between September 1976 and September 2001. Dashed line delineates axis of ebb channel while dotted line defines axis of marginal flood channel on the Bogue Banks shoulder. Table insert lists “shoreline” changes for transects 1-11.